

Message

From: Sohacki, Lynn [sohacki.lynn@epa.gov]
Sent: 4/13/2017 2:43:57 PM
To: Hoban, John [Hoban.John@epa.gov]; Knott, Dave [Knott.Dave@epa.gov]
CC: Cieslak, Kim [cieslak.kim@epa.gov]; Snyder, Jim [Snyder.Jim@epa.gov]
Subject: X400RXX-0003

Hi.

Please replace the fascia on this vehicle and prepare it for driving on the road. The vehicle needs to be roadworthy by 4/21.

Thank you,

Lynn

From: Snyder, Jim
Sent: Thursday, April 13, 2017 10:38 AM
To: Sohacki, Lynn <sohacki.lynn@epa.gov>
Cc: Ball, Joel <ball.joel@epa.gov>
Subject: VW GEN1 -0003 manual test car

Lynn,
The VW diesel Jetta, X400RXX-0003, VIN [Ex. 6 Personal Privacy (PP)] has completed dyno testing and needs to return to roadworthy condition for the on-road PEMS testing. Please have Jacobs re-install the front fascia and anything else needed to drive on-road. Do not remove the Tailpipe flange.

The vehicle is on the stacker , 3rd level.

Jim Snyder
Light-Duty Vehicle Group
Compliance Division
United States Environmental Protection Agency
(734) 214-4946
snyder.jim@epa.gov